



Runway Excursion Incident Involving Cessna C172 trainer Aircraft at Baramati Airfield, Maharashtra

प्रविष्टि तिथि: 09 AUG 2026 6:42PM by PIB Delhi

A runway excursion incident involving a Cessna C172 type aircraft, registration VT-SEX, operated by Academy of Carver Aviation, a DGCA approved Flying Training Organization occurred at Baramati Airfield, Maharashtra, on 09 August 2026 at approximately 12:25 PM.

The aircraft was being operated for a Circuit and Landing Emergencies (CL Emergencies) training exercise. The aircraft was under the command of Capt. Chirag Shashikant Doifode, Flight Instructor with trainee Abhijeet Jundre on board.

The aircraft taxied out at approximately 0639 UTC (1209 IST) for the scheduled training exercise. During the exercise, the aircraft entered the runway through Link Bravo and lined up at the threshold of Runway 29, where a rejected take-off exercise practice was carried out. Subsequently, the aircraft lined up at the threshold of Runway 11 and another rejected take-off exercise was carried out.

During the course of the exercise, the aircraft was unable to stop within the paved runway surface and subsequently veered off the extended paved surface beyond the threshold of Runway 29 towards the right side, resulting in a runway excursion.

There were no injuries or fatalities reported. The aircraft has sustained prima facie damage to the propeller, engine cowling and nose landing gear. A detailed assessment of the damage will be carried out by the competent authorities.

The DGCA Air Safety team is proceeding to the site to conduct a preliminary investigation and ascertain the circumstances and contributing factors leading to the incident. Further information will be shared as and when it is verified and becomes available.

Divyanshu Kumar

(रिलीज़ आईडी: 2296861) आगंतुक पटल : 1282

इस विज्ञप्ति को इन भाषाओं में पढ़ें: Urdu , Marathi , हिन्दी , Gujarati , Tamil , Telugu